



QUESTION RESPONSE

**FOR RFP# 8335
SRWTP Outfall Expansion Joint Repair Project**

SACRAMENTO REGIONAL COUNTY SANITATION DISTRICT

The following answers questions submitted by proposers prior to the question deadline of
4/19/19:

Thank you,

Tamblynn Stewart
Senior Contract Service Officer
Sacramento Regional County Sanitation District

April 22, 2019

Question Response

RFP#8335



Question: Please confirm if the air duct, adjacent to the outfall conduits, contains any water from infiltration. If so, is there a means to dewater the air duct prior to the shutdown work?

Response: The air duct adjacent to the channels does have drains that operations staff regularly checks and opens. There is typically not water in the air duct when it is tested and water is more likely to infiltrate the duct during rain events. The pressure of the air duct (8 psi) generally keeps water from infiltrating the air duct. SRWTP operations staff can test the drains or cycle the drains as needed while the work occurs to confirm there is not significant water in the air duct. The drain can not be left open as it removes the pressure from the channel which could allow additional water to infiltrate the duct.